


NOTES:

1. SEE INSTRUCTION MANUAL FOR OTHER FEEDBACK CONFIGURATIONS.
2. WIRING IS SHOWN FOR EXTEND-IS-FWD. IF RETRACT-IS-FWD, P4 IS REVERSED.
3. FIELD WIRING TERMINAL: #
4. FEEDBACK SIGNAL:
ISA TYPE 4, CLASS L, POWER ISOLATED.



TERMINAL CONNECTIONS FOR REMOTE CONTROL:

EXTEND	LINE TO EXTEND
RETRACT	LINE TO RETRACT
STOP	NONE

17-4205-02o A

SIZE:
A

HAROLD BECK & SONS INC

NEWTOWN INDUSTRIAL COMMONS NEWTOWN, PENNSYLVANIA 18940 USA

TITLE:

**WIRING DIAGRAM GROUP 42-XX5
120 VOLT 2 AUX SWITCHES**

DRAWN:
CHH 10-11-07

SCALE:
NONE

DRAWING NO:

REV:

CHECKED:
GMD 10/15/07

17-4205-02o

A

APPROVED:
JHM 10/16/07

SHEET NO. 1 OF 1

THIS DOCUMENT IS A COPY AND IS NOT THE SOURCE DOCUMENT. INFORMATION IS SUBJECT TO CHANGE WITHOUT NOTICE. THE INFORMATION CONTAINED HEREIN IS COPYRIGHTED BY HAROLD BECK AND SONS, INC. CHANGES TO THE DOCUMENT ARE PROHIBITED. CONTACT A BECK SALES ENGINEER IF A CERTIFIED DRAWING IS REQUIRED.